

TMCC Command Base 9 pin plug breakdown.

The only suitable replacement is the Lionel one. No other supply has been found that has the needed ground pin that acts as part of the TMCC signal...There is an alternative in a pinch - use a similarly sized 12vac wall wart and run a wire from pin 5 of the Command Base rs-232 port to the ground screw of a nearby grounded metal duplex outlet or household electrical ground until you get the right adapter.

